

Volvo Car Customer Service TJ Instruction VCC-376947-56


Title	Safety instructions for rescue work	Page	1 (6)
Action	General safety information	Operation number:	

Issue	Date	Reason
1	2017-04	First issue

Affected vehicles

Model year	Model	Engine	Partner group
2017, 2018	V90 (17-)	B4204T35	Europe
			International
			Nordic

TJ Instruction VCC-376947-56		Page 2 (6)
Safety information		
	location of the differ (for example, pyrothy voltage) found in Vall emergency service familiar with this deactivation or ignition information is not eas general. The interpretation of the service of th	ntains information about and erent types of stored energy rechnical, fuel, and electric volvo's different models. vices personnel should be ocument to avoid accidental on during rescue actions. The exact, it shall be regarded formation shown applies to icles. On right-hand drive earts may have reversed
	at least 30 second the vehicle. This	ergency services nnect the battery and wait ds before starting work on is to prevent inadvertent technical SRS components.
	Applies to vehicle Only disconnect	ency service personnel: es with electrical drivelines: the 12-volt battery, this also nigh voltage system.
	Note! Do not tou components.	ch high-voltage
	between different where several mo	n the members may vary models. In illustrations odels appear with the same ne variant with the hardest s shown.







- 1 . Airbags
- 2 . Danger zone
- 3 . Seat belt pretensioner
- 4 . Reinforcements
- 5 . Fuel
- 6 . Battery
- 7 . High voltage

Orientation view

